











## recommended modification on EASY-STARTER

for engines EOS 100 / 100 Booster / ICI EOS 150 ICI

(not relevant for regular standard starter!)

Due to different circumstances - improper recoil or incorrect angle or extensive vibration or improper tension of the starter rope, or a combination of these conditions - it may happen that the starter rope going into the gap between starter housing and rope spool. In consequence the rope is getting caught by the fins of the magnet wheel and damage to rope, starter mechanism, magnet wheel may occur.

We therefore strongly recommend to conduct the hereby described modification to the EASY-STARTER as per pictures shown.

The necessary part - "arc adapter" - can be received from any EOS engine partner or dealer or from EOS engine Austria directly for free!

For any further information or inquiry write to; sales@eos-engine.com



## www.eos-engine.com



